

# USER MANUAL IRO2

Pyrgeometer with heater





# Warning statements



Putting more than 12 Volt across the sensor wiring can lead to permanent damage to the sensor.



Do not use "open circuit detection" when measuring the sensor output.

ir02 manual v1301 2/43



# Contents

War	ning statements	2
Cont	tents	3
List	of symbols	4
Intr	oduction	5
1	Ordering and checking at delivery	7
1.1	Ordering IR02	
1.2	Included items	7 7
1.3	Quick instrument check	8
2	Instrument principle and theory	8 <b>9</b>
2.1	Pyrgeometer functionality	9
2.2	Solar and longwave radiation	9
2.3	IR02 pyrgeometer design	11
2.4	Typical measurement results	13
2.5	Optional heating	13
2.6	Use as a net radiation sensor	13
3	Specifications of IR02	14
3.1	Specifications of IR02	14
3.2	Dimensions of IRO2	17
4	Standards and recommended practices for use	18
4.1 4.2	Site selection and installation Electrical connection	19
4.2 4.3	Requirements for data acquisition / amplification	20 21
դ.յ <b>5</b>	Making a dependable measurement	22
5.1	The concept of dependability	22
5.2	Reliability of the measurement	23
5.3	Speed of repair and maintenance / instrument lifetime	24
5.4	Uncertainty evaluation	25
6	Maintenance and trouble shooting	26
6.1	Recommended maintenance and quality assurance	26
6.2	Trouble shooting	27
6.3	Calibration and checks in the field	28
6.4	Data quality assurance	28
7	IRO2-TR	29
7.1	Introduction IR02-TR	29
7.2	Dimensions of IR02-TR	31
8	Appendices	34
8.1	Appendix on cable extension / replacement	34
8.2	Appendix on tools for IRO2	35
8.3	Appendix on spare parts for IR02	35
8.4	Appendix on standards for classification and calibration	36
8.5	Appendix on calibration hierarchy  Appendix on metagralogical radiation quantities	36
8.6 8.7	Appendix on meteorological radiation quantities Appendix on terminology / glossary	38 39
8.8	Appendix on conditions of sale: warranty and liability	40
ช.o	FC declaration of conformity	41

ir02 manual v1301 3/43



# List of symbols

Quantities	Symbol	Unit
Voltage output	U	V
Sensitivity at reference conditions	S	$V/(W/m^2)$
Temperature	T	°C
Equivalent blackbody radiative temperature	T	°C
Electrical resistance	$R_{e}$	Ω
Longwave irradiance	Е	W/m <sup>2</sup>
Stefan-Boltzmann constant (5.67 x 10 <sup>-8</sup> )	σ	$W/(m^2 \cdot K^4)$

(see also appendix 8.6 on meteorological quantities)

### **Subscripts**

relating to the atmosphere relating to the ground surface relating to ambient air relating to the instrument body relating to the sensor

ir02 manual v1301 4/43



# Introduction

IR02 is a pyrgeometer suitable for longwave irradiance measurements in meteorological applications. The instrument can be heated, which improves measurement accuracy as it prevents dew deposition on its window.

IR02 measures the longwave or far-infra-red radiation received by a plane surface, in  $W/m^2$ , from a field of view angle of approximately  $150^\circ$ . Longwave radiation is the part of radiation that is not emitted by the sun. The actual field of view angle of IR02 is not the ideal  $180^\circ$ . The reduction of this field of view makes it possible to offer an instrument at an attractive price level, while the accuracy loss is relatively small.

IR02 has a window with a solar blind filter with a cut-on at  $4.5 \times 10^{-6}$  m, making it suitable for day- and night observations.

IR02 pyrgeometer has a high sensitivity. With sufficient input signal a typical datalogger no longer contributes to the uncertainty of the measurement. IR02 also houses an onboard heater. Heating prevents dew deposition and condensation which, when occurring, leads to very large measurement errors.

Using IR02 is easy. It can be connected directly to commonly used data logging systems. The irradiance in  $W/m^2$  is calculated by dividing the IR02 output, a small voltage, by the sensitivity and taking in account the irradiated heat by the sensor itself (Stefan-Boltzmann law). The sensitivity is provided with IR02 on its calibration certificate.

The central measurement equation governing IR02 is:

$$E = U/S + \sigma \cdot (T + 273.15)^4$$
 (Formula 0.1)

The instrument should be used in accordance with the recommended practices of the World Meteorological Organization (WMO).

Suggested use for IR02:

- general meteorological observations
- climatological networks
- agricultural networks

ir02 manual v1301 5/43





**Figure 0.1** *IR02 pyrgeometer with heater* 

Calibration of pyrgeometers used for downward longwave radiation is traceable to the World Infrared Standard Group (WISG). This calibration takes into account the spectral properties of typical downward longwave radiation. As an option, calibration can be made traceable to a blackbody and the International Temperature Scale of 1990 (ITS-90). This alternative calibration is appropriate for measurements of upward longwave radiation (with IR02 pyrgeometers facing down).

Model IR02-TR houses a 4-20 mA transmitter for easy read-out by dataloggers commonly used in the industry. For more information, see the chapter on IR02-TR.

ir02 manual v1301 6/43



# 1 Ordering and checking at delivery

### 1.1 Ordering IR02

The standard configuration of IR02 is with 5 metres cable.

Common options are:

- Longer cable (in multiples of 5 m). Specify total cable length.
- IR02-TR pyrgeometer with heater and 4-20 mA transmitter. Standard setting is 4 mA at -300 W/m² and 20 mA at 100 W/m². Specify setting and total cable length.
- Internal temperature sensor. This can be either a Pt100 (standard configuration) or a  $10 \text{ k}\Omega$  thermistor (optional). Specify respectively T1 or T2.
- Optional calibration to blackbody (ITS-90).

Supply of products is subject to Hukseflux' General Conditions of Sale. The product warranty (involving repair or replacement without charge for product or working hours) is 24 months.

Hukseflux does not accept any liability for losses or damages related to use of the supplied products. See the appendix and Hukseflux' General Conditions of Sale for detailed statements on warranty and liability.

#### 1.2 Included items

Arriving at the customer, the delivery should include:

- pyrgeometer IR02
- cable of the length as ordered
- product certificate matching the instrument serial number
- · any other options as ordered

Please store the certificate in a safe place.

ir02 manual v1301 7/43



# 1.3 Quick instrument check

A quick test of the instrument can be done by using a simple hand held multimeter and a thermal source.

- 1. Check the electrical resistance of the sensor between the green (-) and white (+) wire. Use a multimeter at the 1000  $\Omega$  range. Measure the sensor resistance first with one polarity, than reverse the polarity. Take the average value. The typical resistance of the wiring is 0.1  $\Omega$ /m. Typical resistance should be the typical sensor resistance of 100 to 400  $\Omega$  plus 1.5  $\Omega$  for the total resistance of two wires (back and forth) of each 5 m. Infinite resistance indicates a broken circuit; zero or a low resistance indicates a short circuit.
- 2. Check if the sensor reacts to heat: put the multimeter at its most sensitive range of DC voltage measurement, typically the  $100 \times 10^{-3}$  VDC range or lower. Make sure that the sensor is at 20 °C or lower. Expose the sensor to a strong heat source at a short distance from the window of more than 50 °C, for instance a hot cup of coffee. The signal should read positive and  $> 1 \times 10^{-3}$  V now. In case of using your hand as a heat source, the signal should be significantly lower.
- 3. Inspect the bubble level.
- 4. Check the electrical resistance of the Pt100. This should be in the 100  $\Omega$  range. In case of use of a 10 k $\Omega$  thermistor it should be in the 10<sup>4</sup>  $\Omega$  range
- 5. Check the electrical resistance of the heater. This should be in the 100  $\Omega$  range.
- 6. Inspect the instrument for any damage.

ir02 manual v1301 8/43



# 2 Instrument principle and theory

# 2.1 Pyrgeometer functionality

IR02's scientific name is pyrgeometer. IR02 measures the longwave or far-infra-red (FIR) radiation received by a plane surface, in W/m², ideally from a 180° field of view angle. In meteorological terms pyrgeometers are used to measure "downward and upward longwave irradiance" (WMO definition). In case of IR02 the ideal 180° field of view angle has been reduced to 150°. This makes it possible to offer an instrument at an attractive price level, while the loss of accuracy is relatively small.

As secondary measurands, the sky temperature  $T_{sky}$ , and the equivalent surface (ground) temperature  $T_{surface}$  can be measured. Both are so-called equivalent blackbody radiative temperatures, i.e. temperatures calculated from the pyrgeometer measurement assuming these are uniform-temperature blackbodies with an emission coefficient of 1.


## 2.2 Solar and longwave radiation

Longwave radiation is the part of the radiation budget that is not emitted by the sun. The spectral range of the longwave radiation is not standardised. A practical cut-on is in the range of 4 to 5 x  $10^{-6}$  m (see figure 2.2.1). In meteorology, solar- and longwave radiation are typically measured as separate parameters. The instrument to measure solar radiation is called pyranometer.

In the longwave spectrum, the sky can be seen as a temperature source; colder than ground level ambient air temperature, with its lowest temperatures at zenith, getting warmer (closer to ambient air temperature) at the horizon. The uniformity of this longwave source is much better than that in the range of the solar spectrum, where the sun is a dominant contributor. The "equivalent blackbody" temperature, as a function of zenith angle, roughly follows the same pattern independent of the exact sky condition (cloudy or clear). This explains why for pyrgeometers the directional response is not very critical.

ir02 manual v1301 9/43





**Figure 2.2.1** Atmospheric radiation as a function of wavelength plotted along two logarithmic axes to highlight the longwave radiation. Longwave radiation is mainly present in the 4 to  $50 \times 10^{-6}$  m range, whereas solar radiation is mainly present in the 0.3 to  $3 \times 10^{-6}$  m range. In practice, the two are measured separately using pyrgeometers and pyranometers

The downwelling longwave radiation essentially consists of several components:

- 1. low temperature radiation from the universe, filtered by the atmosphere. The atmosphere is transparent for this radiation in the so-called atmospheric window (roughly the 10 to  $15 \times 10^{-6}$  m wavelength range).
- 2. higher temperature radiation emitted by atmospheric gasses and aerosols.
- 3. in presence of clouds or mist, the low temperature radiation from the universe is almost completely blocked by the water droplets. The pyrgeometer then receives the radiation emitted by the water droplets.

Upwelling longwave irradiance is measured with downfacing instruments. These are presumably looking directly at the surface (absorption and emission of the atmosphere is low over a short distance of around 2 m), which behaves like a normal blackbody. Hukseflux suggests calibrating downfacing instruments against a blackbody rather than having WISG as a reference.



 Table 3.1.1 Specifications of IR02 (continued)

ADDITIONAL SPECIFICATIONS	
Zero offset b (response to 5 K/h change in ambient temperature)	$< \pm 4 \text{ W/m}^2$
Non-stability	< ± 1 % change per year
Non-linearity	$< \pm 2.5 \%$ (100 to 300 W/m <sup>2</sup> , relative to 200 W/m <sup>2</sup>
,	sensor to source exchange)
Measurement range	-300 to +300 W/m <sup>2</sup>
ğ	(sensor to source exchange: U/S)
Tilt dependence	< ± 2 % (0 to 90° at 300 W/m <sup>2</sup> )
Sensor resistance range	100 to 400 Ω
Expected voltage output	application for outdoor measurement of downward longwave irradiance: $-7.5$ to $7.5 \times 10^{-3}$ V
Measurement function / required programming	$E = U/S + \sigma \cdot (T + 273.15)^4$
Measurement function / optional programming for sky temperature	$T_{\text{sky}} = (E_1 / \sigma)^{1/4} + 273.15$
Measurement function / optional	$T_{\text{surface}} = (E_1 / \sigma)^{1/4} + 273.15$
programming for surface temperature	
Required readout	1 differential voltage channel or 1 single ended voltage channel, input resistance $> 10^6~\Omega$ 1 temperature channel
STANDARDS	
Standard governing use of the instrument	WMO-No. 8, Guide to Meteorological Instruments and Methods of Observation, seventh edition 2008, paragraph 7.4 "measurement of total and long-wave radiation"
MOUNTING, CABLING, TRANSPORT	
Standard cable length (see options)	5 m
Cable diameter	5.3 x 10 <sup>-3</sup> m
Cable replacement	IR02 cable is potted and cannot be replaced
Instrument mounting	$2 \times M5$ bolt at $65 \times 10^{-3}$ m centre-to-centre distance on north-south axis
Levelling	bubble level and adjustable levelling feet are included
Levelling accuracy	< 0.4° bubble entirely in ring
IP protection class	IP 67
Gross weight including 5 m cable	0.5 kg
Net weight including 5 m cable	0.3 kg
Packaging	box of (170 x 90 x 230) x 10 <sup>-3</sup> m

ir02 manual v1301 15/43



# 3.1 Specifications of IR02

IR02 pyrgeometer measures the longwave irradiance received by a plane surface, in  $W/m^2$ , from a 150° field of view angle, which approximates the ideal 180° field of view angle. In meteorological terms IR02 measures downward and upward longwave irradiance. Working completely passive, using a thermopile sensor, IR02 generates a small output voltage proportional to the radiation balance between the instrument and the source it faces. It can only be used in combination with a suitable measurement system. The instrument is not subject to classification. It should be used in accordance with the recommended practices of WMO. IR02 measures during both day and night. For high accuracy measurements the user should consider to use the incorporated heater.

**Table 3.1.1** Specifications of IR02

IR02 SPECIFICATIONS	
MEASURANDS	
Measurand	longwave radiation
Measurand in SI radiometry units	longwave irradiance in W/m <sup>2</sup>
Optional measurand	sky temperature
Optional measurand	surface temperature
Spectral range IR02	4.5 to 40 x 10 <sup>-6</sup> m
	(nominal, see product certificate for individual value)
Solar offset	$< 15 \text{ W/m}^2$
	(at 1000 W/m² global horizontal irradiance on the dome)
MAIN SPECIFICATIONS	
Field of city and a	1500
Field of view angle	150°
Response time (95 %)	18 s
Sensitivity (nominal)	15 x 10 <sup>-6</sup> V/(W/m <sup>2</sup> )
Sensitivity range	5 to 15 x 10 <sup>-6</sup> V/(W/m <sup>2</sup> )
Rated operating temperature range	-40 to +80 °C
Temperature dependence	< ± 3 % (-10 to +40 °C)
Temperature sensor	Pt100
Required sensor power	zero (passive sensor)
Heater	12 VDC, 1.5 W
	(see below for details)
Standard cable length	5 m

ir02 manual v1301 14/43



## 2.4 Typical measurement results

Please note that the signal generated by an upfacing pyrgeometer usually has a negative sign.

The most important factors determining downward longwave irradiance are:

- ambient air temperature
- skv condition / cloud cover
- atmospheric moisture content

**Table 2.4.1** Expected pyrgeometer output U/S at different ambient air temperatures,  $T_{ambient}$ , and at different cloud conditions. Under clear sky conditions the U/S is around -100 W/m² while under cloudy conditions it will be close to 0 W/m². Also calculated: the sky temperature,  $T_{sky}$ , and the longwave downward irradiance E.

#### **EXPECTED PYRGEOMETER OUTPUT CONDITIONS**

T <sub>ambient</sub>	Sky condition	U/S	T <sub>skv</sub>	E
[°C]	[cloudy], [clear]	[W/m <sup>2</sup> ]	[°C]	[W/m <sup>2</sup> ]
-20	cloudy	0	-20	232
-20	clear sky	-100	-53	132
0	cloudy	0	+0	314
0	clear sky	-100	-24	214
+30	cloudy	0	+30	477
+30	clear sky	-100	+12	377

# 2.5 Optional heating

A low-power heater is located in the body of the pyrgeometer. The heater is not necessarily switched on; recommended operation is to activate the heater when there is a risk of dew deposition.

#### 2.6 Use as a net radiation sensor

Two pyrgeometers mounted back to back may be used to measure net longwave radiation. Net longwave radiation is defined as downwelling minus upwelling longwave irradiance. In case the two instruments are thermally coupled, the body temperatures of the instruments are identical. In that case the body temperature cancels from the equation for the net radiation. However for calculation of sky temperature and surface temperature the instrument temperature still needs to be measured. See also model NR01, a 4-component net radiometer.

ir02 manual v1301



A pyrgeometer should have a so-called "directional response" (older documents mention "cosine response") that is as close as possible to the ideal cosine characteristic.

In order to attain the proper directional and spectral characteristics, a pyrgeometer's main components are:

- a thermal sensor with black coating. It has a flat spectrum covering the 0.3 to 50 x 10<sup>-6</sup> m range, and has a near-perfect directional response. The coating absorbs all longwave radiation and, at the moment of absorption, converts it to heat. The heat flows through the sensor to the sensor body. The thermopile sensor generates a voltage output signal that is proportional to the irradiance exchange between sensor and source. The sensor not only absorbs, but also irradiates heat as a blackbody.
- a silicon window. This dome limits the spectral range from 1.0 to  $40 \times 10^{-6}$  m (cutting off the part below  $1.0 \times 10^{-6}$  m), while preserving as much as possible the ideal  $180^{\circ}$  field of view angle. Another function of the window or dome is that it shields the thermopile sensor from the environment (convection, rain).
- a solar blind interference coating deposited on the window: this coating limits the spectral range. It now becomes 4.5 to 40 x  $10^{-6}$  m (cutting off the part below 4.5 x  $10^{-6}$  m).

Pyrgeometers can be manufactured to different specifications and with different levels of verification and characterisation during production. Hukseflux also manufactures higher accuracy pyrgeometers; see pyrgeometer model IR20.

ir02 manual v1301



# 2.3 IR02 pyrgeometer design




Figure 2.3.1 Overview of IR02 pyrgeometer:

- (1) cable, (standard length 5 metres, optional longer cable)
- (2) cable gland
- (3) window with solar blind filter
- (4) sensor (below window)
- (5) sensor body
- (6) levelling feet
- (7) mounting hole
- (8) bubble level

By definition a pyrgeometer should not measure solar radiation, and in the longwave have a spectral selectivity that is as "flat" as possible.

In an irradiance measurement by definition the response to "beam" radiation varies with the cosine of the angle of incidence; i.e. it should have full response when the radiation hits the sensor perpendicularly (normal to the surface, 0° angle of incidence), zero response when the source is at the horizon (90° angle of incidence, 90° zenith angle), and 50 % of full response at 60° angle of incidence.

ir02 manual v1301 11/43




 Table 3.1.1 Specifications of IR02 (started on previous pages)


HEATING	
Heater operation	the heater is not necessarily switched on; recommended operation is to activate the heater when there is a risk of dew deposition
Required heater power	1.5 W at 12 VDC
Heater resistance	95 Ω
Steady state zero offset caused by heating	0 W/m <sup>2</sup>
CALIBRATION	
Calibration traceability	to WISG
Optional traceability	to blackbody (ITS-90 )
Calibration hierarchy	from WISG through Hukseflux internal calibration procedure employing a blackbody
Calibration method	indoor calibration under a blackbody, by comparison reference pyrgeometer traceable to WISG
Calibration uncertainty	< 7 % (k = 2)
Recommended recalibration interval	2 years
Reference conditions	horizontal mounting, atmospheric longwave irradiance, clear sky nights, 20 °C
Validity of calibration	based on experience the instrument sensitivity will not change during storage. During use under exposure to solar radiation the instrument "non-stability" specification is applicable.  Hukseflux recommends ITS-90 traceable calibration for upward longwave irradiance measurement.
MEASUREMENT ACCURACY	
Uncertainty of the measurement	statements about the overall measurement uncertainty can only be made on an individual basis. See the chapter on uncertainty evaluation
Achievable uncertainty (95 % confidence level) daily totals	± 15 % (Hukseflux' own estimate)
VERSIONS / OPTIONS	
Longer cable, in multiples of 5 m	option code = total cable length
Calibration	optional to blackbody (ITS-90 )
4-20 mA transmitter	creating a 4-20 mA output signal, option code = TR, with adapted housing
	standard setting is 4 $\times$ 10 <sup>-6</sup> A at -300 W/m <sup>2</sup> and 20 $\times$ 10 <sup>-6</sup> A at +100 W/m <sup>2</sup> heater and internal temperature sensor directly
	connected to cable wire for specifications see the chapter on IR02-TR
Internal temperature sensor	measuring the body temperature: version code = T1 for Pt100 DIN class A,
	version code = T2 for thermistor 10 k $\Omega$ at 25 °C
Longer cable, in multiples of 5 m	option code = total cable length

ir02 manual v1301 16/43



# 3.2 Dimensions of IR02





**Figure 3.2.1** Dimensions of IRO2 in 10<sup>-3</sup> m

ir02 manual v1301 17/43



# 4 Standards and recommended practices for use

Pyrgeometers are not subject to standardisation.

The World Meteorological Organization (WMO) is a specialised agency of the United Nations. It is the UN system's authoritative voice on the state and behaviour of the earth's atmosphere and climate. WMO publishes WMO-No. 8; Guide to Meteorological Instruments and Methods of Observation, in which paragraph 7.4 covers "measurement of total and long-wave radiation".

For ultra high accuracy measurements, the following manual may serve as a reference: Baseline Surface Radiation Network (BSRN) Operations Manual, Version 2.1, L. J. B. McArthur, April 2005, WCRP-121, WMO/TD-No. 1274.

This manual also includes chapters on installation (paragraph 4.1) and calibration (paragraph 8.4).

ir02 manual v1301



# 4.1 Site selection and installation

**Table 4.1.1** Recommendations for installation of pyrgeometers

Location	the horizon should be as free from obstacles as possible.
Mechanical mounting / thermal insulation	preferably use connection by bolts to the bottom plate of the instrument. A pyrgeometer is sensitive to thermal shocks. Do not mount the instrument with the body in direct thermal contact to the mounting plate (so always use the levelling feet also if the mounting is not horizontal), do not mount the instrument on objects that become very hot (black coated metal plates).
Instrument mounting with 2 bolts	$2 \times M5$ bolt at $65 \times 10^{-3}$ m centre-to-centre distance on north-south axis, connection through the pyrgeometer flange.
Performing a representative measurement	the pyrgeometer measures the solar radiation in the plane of the sensor. This may require installation in a tilted or inverted position. The sensor surface (sensor bottom plate) should be mounted parallel to the plane of interest.  In case a pyrgeometer is not mounted horizontally or in case the horizon is obstructed, the representativeness of the location becomes an important element of the measurement. See the chapter on uncertainty evaluation.
Levelling	in case of horizontal mounting only use the bubble level and levelling feet.
Instrument orientation	by convention with the cable exit pointing to the nearest pole (so the cable exit should point north in the northern hemisphere, south in the southern hemisphere).
Installation height	in case of inverted installation, WMO recommends a distance of 1.5 m between soil surface and sensor (reducing the effect of shadows and in order to obtain good spatial averaging).

ir02 manual v1301 19/43



#### 4.2 Electrical connection

In order to operate, a pyrgeometer should be connected to a measurement system, typically a so-called datalogger. IR02 is a passive sensor that does not need any power. Cables generally act as a source of distortion, by picking up capacitive noise. We recommend keeping the distance between a datalogger or amplifier and the sensor as short as possible. For cable extension, see the appendix on this subject.

**Table 4.2.1** The electrical connection of IR02. The heater is not necessarily used. The temperature sensor must be used.


PIN	WIRE	IRO2
1	Red	Pt100 [+]
2	White	Pt100 [+]
3	Blue	Pt100 [-]
4	Green	Pt100 [-]
5	Brown	heater
6	Yellow	heater
7	Black	ground
8	Pink	signal [+]
9	Grey	signal [–]

Note 1: optional 10  $k\Omega$  thermistors are internally connected in a 4-wire configuration like the Pt100 but usually connected to electronics used in 2-wire configuration.

Note 2: the heater is not necessarily connected. In case it is connected, the polarity of the connection is not important.

Note 3: signal wires are insulated from ground wire and from the sensor body. Insulation resistance is tested during production and larger than  $1 \times 10^6 \Omega$ .

Note 4: ground is connected to the connector, the sensor body and the shield of the wire.



**Figure 4.2.1** Electrical diagram of the internal wiring of IR02. The shield is connected to the sensor body.



## 4.3 Requirements for data acquisition / amplification

The selection and programming of dataloggers is the responsibility of the user. Please contact the supplier of the data acquisition and amplification equipment to see if directions for use with the IRO2 are available.

In case programming for similar instruments is available, this can typically also be used. IR02 can usually be treated in the same way as other thermopile pyrgeometers.

**Table 4.3.1** Requirements for data acquisition and amplification equipment for IR02 in the standard configuration

Capability to measure small voltage signals	preferably: better than $5 \times 10^{-6} \text{ V}$ uncertainty Minimum requirement: $20 \times 10^{-6} \text{ V}$ uncertainty (valid for the entire expected temperature range of the acquisition / amplification equipment)
Capability for the data logger or the software	to store data, and to perform division by the sensitivity to calculate the longwave irradiance. $E = U/S + \sigma \cdot (T + 273.15)^4 \text{ (Formula 0.1)}$ (see also optional measurands)
Data acquisition input resistance	$> 1 \times 10^6 \Omega$
Open circuit detection (WARNING)	open-circuit detection should not be used, unless this is done separately from the normal measurement by more than 5 times the sensor response time and with a small current only. Thermopile sensors are sensitive to the current that is used during open circuit detection. The current will generate heat, which is measured and will appear as an offset.
Capability to measure temperature	a Pt100 (or optional thermistor) must be read-out. Required accuracy of the readout is $\pm$ 0.2 °C, which results in around 1 W/m <sup>2</sup> uncertainty of the irradiance measurement.
Capability to power the heater (OPTIONAL)	IR02 has a 12 VDC, 1.5 W heater on board, which may optionally be activated to keep the instrument above dew point. Some users prefer to have the heater on full time, others prefer to switch it on during nighttime only.

ir02 manual v1301 21/43



# 5 Making a dependable measurement

# 5.1 The concept of dependability

A measurement with a pyrgeometer is called "dependable" if it is reliable, i.e. measuring within required uncertainty limits, for most of the time and if problems, once they occur, can be solved quickly.

The requirements for a measurement with a pyrgeometer may be expressed by the user as:

- required uncertainty of the measurement (see following paragraphs)
- requirements for maintenance and repairs (possibilities for maintenance and repair including effort to be made and processing time)
- a requirement to the expected instrument lifetime (until it is no longer feasible to repair)

It is important to realise that the uncertainty of the measurement is not only determined by the instrument but also by the way it is used.

In case of pyrgeometers, the measurement uncertainty as obtained during outdoor measurements is a function of:

- the instrument properties
- the calibration procedure / uncertainty
- the presence of natural sunlight (involving the instrument specification of solar offset)
- the measurement conditions (such as tilting, ventilation, shading, heating, instrument temperature)
- maintenance (mainly fouling and deposition of water)
- the environmental conditions\* (such as temperature, position of the sun, presence of clouds, horizon, representativeness of the location)

Therefore statements about the overall measurement uncertainty under outdoor conditions can only be made on an individual basis, taking all these factors into account.

\* defined at Hukseflux as all factors outside the instrument that are relevant to the measurement such as the cloud cover (presence or absence of direct radiation), sun position, the local horizon (which may be obstructed) or condition of the ground (when inverted). The environmental conditions also involve the question whether or not the measurement at the location of measurement is representative of the quantity that should be measured.



## 5.2 Reliability of the measurement

A measurement is reliable if it measures within required uncertainty limits for most of the time. We distinguish between two causes of unreliability of the measurement:

- related to the reliability of the pyrgeometer and its design, manufacturing, calibration (hardware reliability).
- related to the reliability of the measurement uncertainty (measurement reliability), which involves hardware reliability as well as condition of use.

Most of the hardware reliability is the responsibility of the instrument manufacturer. The reliability of the measurement however is a joint responsibility of instrument manufacturer and user. As a function of user requirements, taking into account measurement conditions and environmental conditions, the user will select an instrument of a certain class, and define maintenance support procedures.

In many situations there is a limit to a realistically attainable accuracy level. This is due to conditions that are beyond control once the measurement system is in place. Typical limiting conditions are:

- the measurement conditions, for instance when working at extreme temperatures when the instrument temperature is at the extreme limits of the rated temperature range.
- the environmental conditions, for instance when installed at a sub-optimal measurement location with obstacles in the field of view.
- the environmental conditions, for instance when assessing net radiation, the downfacing pyrgeometer measurement may not be representative of irradiance received in that particular area.

The measurement reliability can be improved by maintenance support. Important aspects are:

- dome fouling by deposition of dust, dew, rain or snow. With pyrgeometers the most
  important source of unreliability is deposition of water on the dome. Water completely
  blocks the longwave radiation flux between sensor and sky. In particular at clear
  nights this causes very large errors. Water deposition under clear-sky nighttime
  conditions can largely be prevented by using the instrument heater. Fouling results in
  undefined measurement uncertainty (sensitivity and directional error are no longer
  defined). This should be solved by regular inspection and cleaning.
- sensor instability. Maximum expected sensor aging is specified per instrument as its non-stability in [% change / year]. In case the sensor is not recalibrated, the uncertainty of the sensitivity gradually will increase. This is solved by regular recalibration.
- moisture condensing under pyrgeometer domes resulting in a slow change of sensitivity (within specifications). For non-serviceable sensors like Hukseflux' flat window pyrgeometers, such as model IR02, this may slowly develop into a defect. For research-grade model IR20 extra desiccant (in a set of 5 bags in an air tight bag) is available.



• One of the larger errors in the daytime measurement of downwelling longwave irradiance is the offset caused by solar radiation; the "solar offset". Errors due to solar offset, are of the order of +15 W/m² at 1000 W/m² global horizontal irradiance. For ultra-high accuracy measurements this offset can be reduced by around 60% by "shading", which means preventing the direct radiation to reach the instrument. Shading is typically done by using a shading disk on a solar tracker. Shading is often applied with research-grade pyrgeometers like Hukseflux model IR20. The overall accuracy of model IR02 does not justify use of shading.

Another way to improve measurement reliability is to introduce redundant sensors.

• The use of redundant instruments allows remote checks of one instrument using the other as a reference, which leads to a higher measurement reliability.

## 5.3 Speed of repair and maintenance / instrument lifetime

Dependability is not only a matter of reliability but also involves the reaction to problems; if the processing time of service and repairs is short, this contributes to the dependability.

Hukseflux pyrgeometers are designed to allow easy maintenance and repair. The main maintenance actions are:

 replacement of cabling and cable gland; please note that with IR02 the cable is potted inside the cable gland.

For optimisation of dependability a user should:

- estimate the expected lifetime of the instrument
- design a schedule of regular maintenance
- design a schedule of repair or replacement in case of defects

When operating multiple instruments in a network Hukseflux recommends keeping procedures simple and having a few spare instruments to act as replacements during service, recalibrations and repair.

Hukseflux pyrgeometers are designed to be suitable for the intended use for at least 5 years under normal meteorological conditions. Factory warranty (granting free of charge repair) for defects that are clearly traceable to errors in production is 2 years.

The "product expected lifetime" is defined as the minimum number of years of employment with normal level of maintenance support, until the instrument is no longer suitable for its intended use (cannot be repaired). For pyrgeometers, the product expected lifetime depends heavily on the environmental conditions. Examples of environments with reduced expected lifetime are areas with high levels of air pollution and areas with high levels of salt in the air. Both cause enhanced corrosion. It is not possible to give a generally applicable statement about expected lifetime. In Hukseflux'

ir02 manual v1301 24/43



experience it is not realistic to expect a lifetime longer than 10 years except in very dry environments such as very dry tropical or polar climates.

## 5.4 Uncertainty evaluation

The uncertainty of a measurement under outdoor or indoor conditions depends on many factors, see paragraph 1 of this chapter. It is not possible to give one figure for pyrgeometer measurement uncertainty. The work on uncertainty evaluation is "in progress". There are several groups around the world participating in standardisation of the method of calculation. The effort aims to work according to the guidelines for uncertainty evaluation (according to the "Guide to Expression of Uncertainty in Measurement" or GUM).

The main ingredients of the uncertainty evaluation for pyrgeometers are:

- Calibration uncertainty, which is in the order of  $\pm 7$  % (k = 2) for upfacing instruments measuring downward longwave irradiance
- Calibration uncertainty, which is larger for other than upfacing instruments; for downfacing instruments a blackbody calibration seems preferable. Blackbody calibration will result in a lower sensitivity, S, than WISG traceable calibraton.
- Errors due to water deposition at clear nights; these completely block the longwave irradiance exchange between pyrgeometer and may cause the signal U/S to change from a large negative value (-100 W/m<sup>2</sup>) to around 0 W/m<sup>2</sup>. Water deposition at clear nights may largely be avoided by using the on-board heater of IRO2.
- Errors due to solar offset, which is of the order of +15 W/m<sup>2</sup> at 1000 W/m<sup>2</sup> global horizontal irradiance. This uncertainty is not taken into account in the WISG calibration of the reference instrument.
- Errors due to the choice of the cut-on wavelength of the pyrgeometer. Depending on the atmospheric water content, the pyrgeometer will block a variable percentage of the downward longwave irradiance. This causes an uncertainty of the sensitivity S. With IRO2, this uncertainty is already taken into account in the WISG calibration of the reference instrument.
- Errors due to instrument non-stability. This is now estimated at  $< \pm 1$  % change per year. The main factor in instrument non-stability is the aging of the pyrgeometer solar blind filter.
- Errors due to the temperature measurement T. For this a Pt100 or optional 10 k $\Omega$  thermistor must be read-out. Required accuracy of the readout is  $\pm 0.2$  °C, which results in around 1 W/m² uncertainty of the irradiance measurement. To this the uncertainty of the thermistor itself should be added. In measurement of net radiation, in case the upfacing and downfacing instruments are thermally coupled, the temperature measurement (and also its uncertainty) cancel from the equation.



# Table 7.1.1 Specifications of IR02-TR

### **IR02-TR SPECIFICATIONS**

Description	pyrgeometer with heater and with 4-20 mA transmitter
Transmitted range	-300 to +100 W/m <sup>2</sup>
Output signal	4 to 20 x 10 <sup>-3</sup> A
Principle	2-wire current loop
Supply voltage	7.2 to 35 VDC
Options	adapted transmitted range longer cable, in multiples of 5 m
Mounting	2 x M5 bolt at 65 mm centre-to-centre distance on north-south axis, or 1 x M6 bolt at the centre of the instrument, connection from below under the bottom plate of the instrument

**Table 7.1.2** Requirements for data acquisition and amplification equipment with the IRO2-TR configuration

Capability to - measure 4-20 mA or - measure currents or - measure voltages	The IR02-TR has a 4-20 mA output as well as a temperature sensor (see next row) which both must be read out. Concerning the 4-20 mA signal, there are several possibilities to handle this signal. It is important to realise that the signal wires not only act to transmit the signal but also act as power supply. Some dataloggers have a 4-20 mA input. In that case the connection can be directly made. Some dataloggers have the capability to measure currents. In some cases the datalogger accepts a voltage input. Usually a 100 $\Omega$ precision resistor is used to convert the current to a voltage (this will then be in the 0.4 – to 2 VDC range). This resistor must be put in the + wire of the sensor. In the two latter cases the user must check that the low side of the input channel is connected to ground, and the high side to a positive voltage in the required range.
Capability to - measure temperatures	Depending on the version this may be Pt100 or a 10 $\mbox{k}\Omega$ thermistor

ir02 manual v1301 30/43



#### 7.1 Introduction IR02-TR

As a version of IR02, Hukseflux offers model IR02-TR: a pyrgeometer with heater and 4-20 mA transmitter.

IR02-TR houses a 4-20 mA transmitter for easy read-out by dataloggers commonly used in the industry.

Using IR02-TR is easy. The pyrgeometer can be connected directly to commonly used data logging systems. The irradiance in W/m² is calculated by using the transmitter's output and the temperature reading. The latter can either be a Pt100 or a 10 k $\Omega$  thermistor, depending on the ordered version.

In IR02-TR's standard configuration, the 4 to 20 mA output corresponds to a transmitted range of -300 to  $+100 \text{ W/m}^2$ . This range can be adjusted at the factory upon request.



Figure 7.1.1 IR02-TR pyrgeometer with heater and 4-20 mA transmitter



#### 6.3 Calibration and checks in the field

Recalibration of field pyrgeometers is typically done by comparison in the field to a reference pyrgeometer. There is no standard for this procedure.

Hukseflux recommendation for re-calibration: if possible, perform calibration indoor by comparison to an identical or a higher class reference instrument, under nighttime as well as daytime conditions. Use nighttime data only to determine S.

Hukseflux main recommendations for field intercomparisons are:

- 1) perform field calibration during several days; 2 to 3 days and if possible under cloudless conditions.
- 2) to take a reference of the same brand and type as the field pyrgeometer or a pyrgeometer of a higher class, and
- 3) to connect both to the same electronics, so that electronics errors (also offsets) are eliminated.
- 4) to mount all instruments on the same platform, so that they have the same body temperature.
- 5) to analyse downward irradiance values at nighttime only to determine S.
- 6) to analyse the daytime data, independently, and look at the residuals between the calibration reference and calibrated instrument as a function of solar irradiance. The solar offset can serve as a quality indicator of the pyrgeometer filter condition.

# 6.4 Data quality assurance

Quality assurance can be done by:

- analysing trends in longwave irradiance signal
- plotting the measured irradiance against mathematically generated expected values
- comparing irradiance measurements between sites
- analysis of daytime signals against solar irradiance

The main idea is that one should look out for any unrealistic values. There are programs on the market that can semi-automatically perform data screening:

See http://www.dqms.com



## 6.2 Trouble shooting

#### Table 6.2.1 Trouble shooting for IR02

The sensor does not give any signal

Check the electrical resistance of the sensor between the green (-) and white (+) wire. Use a multimeter at the 1000  $\Omega$  range. Measure the sensor resistance first with one polarity, than reverse the polarity. Take the average value. The typical resistance of the wiring is 0.1  $\Omega/m$ . Typical resistance should be the typical sensor resistance of 100 to 400  $\Omega$  plus 1.5  $\Omega$  for the total resistance of two wires (back and forth) of each 5 m. Infinite resistance indicates a broken circuit; zero or a low resistance indicates a short circuit.

Check if the sensor reacts to heat: put the multimeter at its most sensitive range of DC voltage measurement, typically the  $100 \times 10^{-3}$  VDC range or lower. Make sure that the sensor is at 20 °C or lower. Expose the sensor to a strong heat source at a short distance from the window of more than 50 °C, for instance a hot cup of coffee. The signal should read positive and >  $1 \times 10^{-3}$  V now. In case of using your hand as a heat source, the signal should be significantly lower. Check the data acquisition by applying a  $1 \times 10^{-6}$  V source to it in the  $1 \times 10^{-6}$  V range.

The sensor signal is unrealistically high or low.

Check if the measurement function, has been implemented properly. Please note that each sensor has its own individual calibration factor and constants, as documented in its production certificate.

Check the electrical resistance of the Pt100. This should be in the 100  $\Omega$  range. In case of use of the optional 10 k $\Omega$  thermistor it should be in the 10<sup>4</sup>  $\Omega$  range Check if the pyrgeometer has a clean window.

Check the location of the pyrgeometer; are there any obstructions / sources that could explain the measurement result.

Check the condition of the wiring at the logger. Check the cable condition looking for cable breaks.

Check the range of the data logger; signal is usually negative (this could be out of range) or the amplitude could be out of range.

Check the data acquisition by applying a 1 x  $10^{-6}$  V source to it in the 1 x  $10^{-6}$  V range. Look at the output. Check if the output is as expected.

Check the data acquisition by short circuiting the data acquisition input with a 100 to 1000  $\Omega$  resistor. Look at the output. Check if the output is close to 0 W/m<sup>2</sup>.

The sensor signal shows unexpected variations

Check the presence of strong sources of electromagnetic radiation (radar, radio etc.)

Check the condition of the shielding. Check the condition of the sensor cable.

Check if the cable is not moving during the measurement

The instrument shows internal condensation.

In case of condensation of droplets: disassemble the instrument and dry out the parts.

The instrument shows persistent internal condensation

Arrange to send the sensor back to Hukseflux for diagnosis.



# 6 Maintenance and trouble shooting

# 6.1 Recommended maintenance and quality assurance

IR02 can measure reliably at a low level of maintenance in most locations. Usually unreliable measurements will be detected as unreasonably large or small measured values. As a general rule this means that regular visual inspection combined with a critical review of the measured data, preferably checking against other measurements, is the preferred way to obtain a reliable measurement.

**Table 6.1.1** Recommended maintenance of IR02. If possible the data analysis and cleaning (1 and 2) should be done on a daily basis.

MINIMUM RECOMMENDED PYRGEOMETER MAINTENANCE						
-	INTERVAL	SUBJECT	ACTION			
1	1 week	data analysis	compare measured data to maximum possible / maximum expected irradiance and to other measurements nearby (redundant instruments). Also historical seasonal records can be used as a source for expected values. Look for any patterns and events that deviate from what is normal or expected.			
2	2 weeks	cleaning	use a soft cloth to clean the dome of the instrument, persistent stains can be treated with soapy water or alcohol			
3	6 months	inspection	inspect cable quality, inspect cable glands, inspect mounting position, inspect cable, clean instrument, clean cable, inspect levelling, change instrument tilt in case this is out of specification, inspect mounting connection.			
4	2 years	recalibration	recalibration by side-by-side comparison to a higher standard instrument in the field			
5		lifetime assessment	judge if the instrument should be reliable for another 2 years, or if it should be replaced			
6	6 years	parts replacement	if applicable / necessary replace the parts that are most exposed to weathering; cable & cable gland, sun screen. NOTE: use Hukseflux approved parts only.			
7		internal inspection	if applicable: open instrument and inspect / replace O-rings; dry internal cavity around the circuit board			
8		recalibration	recalibration by side-by-side comparison to a higher standard instrument at the manufacturer or a reference institute. Also recalibrate the temperature sensor			

ir02 manual v1301 26/43



# 7.2 Dimensions of IR02-TR





Figure 7.2.1 Overview of IR02-TR:

- (1) cable, (standard length 5 metres, optional longer cable)
- (2) cable gland
- (3) window with solar blind filter
- (4) sensor (below window)
- (5) sensor body
- (6) transmitter housing
- (7) levelling feet
- (8) bubble level





**Figure 7.2.2** Dimensions of IR02-TR in 10<sup>-3</sup> m

ir02 manual v1301 32/43



ir02 manual v1301 33/43



## 8.1 Appendix on cable extension / replacement

IR02 cable is potted and cannot be replaced.

The cable gland plus cable assembly may be completely removed and replaced by a similar assembly. Please consult Hukseflux for instructions on cable preparation or use Hukseflux-supplied parts.

IR02 is equipped with one cable. Keep the distance between data logger or amplifier and sensor as short as possible. Cables act as a source of distortion by picking up capacitive noise. In an electrically "quiet" environment the IR02 cable can however be extended without problem to 100 meters. If done properly, the sensor signal, although small, will not significantly degrade because the sensor resistance is very low (so good immunity to external sources) and because there is no current flowing (so no resistive losses). Cable and connection specifications are summarised below.

NOTE: the body of IR02 contains connector blocks that can be used for the internal connection of a new cable. See the chapter on electrical connections.

**Table 8.1.1** Preferred specifications for cable extension of IR02

General	Please consult Hukseflux for instructions or use Hukseflux-supplied parts.			
Cable	8-wire, shielded, with copper core			
Sealing	sealed at the sensor side against humidity ingress			
Core resistance	< 0.1 Ω/m			
Length	cables should be kept as short as possible, in any case the total cable length should be less than 100 m			
Outer sheet	specified for outdoor use			
Connection	either solder the new cable core and shield to the original sensor cable, and make a waterproof connection using cable shrink, or use gold plated waterproof connectors. Always connect shield.			

ir02 manual v1301 34/43



# 8.2 Appendix on tools for IR02

#### **Table 8.2.1** *Specifications of tools for IR02*

tooling required for cable gland fixation and removal	spanner size 15 x 10 <sup>-3</sup> m
tooling required for wire fixation and removal (internal wiring inside IR02 body)	screwdriver blade width 2 x 10 <sup>-3</sup> m
tooling for removal of bottom cap (locking plug)	plate for slot of 15 by 2 x 10 <sup>-3</sup> m (5 EURO CENT coin )

# 8.3 Appendix on spare parts for IR02

- Levelling feet (set of 3) (socket head cap screw M5 x 20, Aluminium)
- IR02 cable (specify length in multiples of 5 m) potted to cable gland
- Bottom cap of IR02 with 0-ring (locking plug M32 x 1.5 plus O-ring 47 x 2)

ir02 manual v1301 35/43



MICC	North Table Dad Chandard Crave Change of a management and by DN					
WISG	World Infra Red Standard Group. Group of pyrgeometers, maintained by PMOD Davos Switzerland that forms the reference for calibration of pyrgeometers.					
	WISG is traceable to international standards through an absolute sky scanning					
	radiometer. WISG has been formally recognised by the World Meteorological					
	Organisation WMO as "interim WMO Pyrgeometer Infrared Reference".					
Sky	equivalent blackbody radiative temperature of the sky; i.e. the temperature					
temperature	calculated from pyrgeometer data measuring downwelling longwave radiation,					
temperature						
	assuming the sky behaves as a blackbody with an emission coefficient of 1.					
Surface	equivalent blackbody radiative temperature of the surface; i.e. the temperature					
temperature	calculated from pyrgeometer data measuring upwelling longwave radiation,					
temperature						
	assuming the ground behaves as a blackbody with an emission coefficient of 1.					

# 8.8 Appendix on conditions of sale: warranty and liability

Delivery of goods is subject to Hukseflux General Conditions of Sale. Hukseflux has the following warranty and liability policy:

Hukseflux guarantees the supplied goods to be new, free from defects related to bad performance of materials and free from faults that are clearly related to production and manufacturing. Warranty on products is valid until 24 months after transfer of ownership. The warranty does not apply if the application involves significant "wear and tear", if it involves use outside the specified range of application, or if it involves accidental damage or misuse. The warranty expires when anyone other than Hukseflux makes modifications to or repairs the products.

Hukseflux is in no event liable for damages, to its customers or anyone claiming through these customers, associated to the goods or services it supplies.

ir02 manual v1301 40/43



# 8.7 Appendix on terminology / glossary

**Table 8.7.1** *Definitions and references of used terms* 

TERM	DEFINITION (REFERENCE)				
Solar energy or solar radiation	solar energy is the electromagnetic energy emitted by the sun. Solar energy is also called solar radiation and shortwave radiation. The solar radiation incident on the top of the terrestrial atmosphere is called extra-terrestrial solar radiation; 97 % of which is confined to the spectral range of 290 to 3 000 x $10^{-9}$ m. Part of the extra-terrestrial solar radiation penetrates the atmosphere and directly reaches the earth's surface, while part of it is scattered and / or absorbed by the gas molecules, aerosol particles, cloud droplets and cloud crystals in the atmosphere. The former is the direct component, the latter is the diffuse component of the solar radiation. (ref: WMO, Hukseflux)				
Hemispherical solar radiation	solar radiation received by a plane surface from a 180 ° field of view angle (solid angle of 2 \(\pi\) sr).(ref: ISO 9060)				
Global solar radiation	the solar radiation received from a 180° field of view angle on a horizontal surface is referred to as global radiation. Also called GHI. This includes radiation received directly from the solid angle of the sun's disc, as well as diffuse sky radiation that has been scattered in traversing the atmosphere. (ref: WMO) Hemispherical solar radiation received by a horizontal plane surface. (ref: ISO 9060)				
Plane-of-array irradiance	also POA: hemispherical solar irradiance in the plane of a PV array. (ref: ASTM E2848-11 / IEC 61724)				
Direct solar radiation	radiation received from a small solid angle centred on the sun's disc, on a given plane. (ref: ISO 9060)				
Terrestrial or longwave radiation	radiation not of solar origin but of terrestrial and atmospheric origin and having longer wavelengths (3 000 to 100 000 x $10^{-9}$ m). In case of downwelling E <sub>1</sub> also the background radiation from the universe is involved, passing through the "atmospheric window". In case of upwelling E <sub>1</sub> , composed of longwave electromagnetic energy emitted by the earth's surface and by the gases, aerosols and clouds of the atmosphere; it is also partly absorbed within the atmosphere. For a temperature of 300 K, 99.99 % of the power of the terrestrial radiation has a wavelength longer than 3 000 x $10^{-9}$ m and about 99 per cent longer than 5 000 x $10^{-9}$ m. For lower temperatures, the spectrum shifts to longer wavelengths. (ref: WMO)				
World Radiometric Reference (WRR)	measurement standard representing the SI unit of irradiance with an uncertainty of less than $\pm$ 0.3 % (see the WMO Guide to Meteorological Instruments and Methods of Observation, 1983, subclause 9.1.3). The reference was adopted by the World Meteorological Organization (WMO) and has been in effect since 1 July 1980. (ref: ISO 9060)				
Albedo	ratio of reflected and incoming solar radiation. Dimensionless number that varies between 0 and 1. Typical albedo values are: $< 0.1$ for water, from 0.1 for wet soils to 0.5 for dry sand, from 0.1 to 0.4 for vegetation, up to 0.9 for fresh snow.				
Angle of incidence	angle of radiation relative to the sensor measured from normal incidence (varies from 0° to 90°).				
Zenith angle	angle of incidence of radiation, relative to zenith. Equals angle of incidence for horizontally mounted instruments				
Azimuth angle	angle of incidence of radiation, projected in the plane of the sensor surface. Varies from 0° to 360°. 0 is by definition the cable exit direction, also called north, west is + 90°.				
Sunshine duration	sunshine duration during a given period is defined as the sum of that sub-period for which the direct solar irradiance exceeds 120 $\text{W/m}^2$ . (ref: WMO)				

ir02 manual v1301 39/43



## 8.6 Appendix on meteorological radiation quantities

A pyrgeometer measures longwave irradiance. The time integrated total is called radiant exposure.

**Table 8.6.1** Meteorological radiation quantities as recommended by WMO (additional symbols by Hukseflux Thermal Sensor). POA stands for Plane of Array irradiance. The term originates from ASTM and IEC standards.

SYMBOL	DESCRIPTION	CALCULATION	UNITS	ALTERNATIVE EXPRESSION	
E	downward irradiance	$E = E_g + E_l$	W/m²		
Н	downward radiant exposure for a specified time interval	$H = H_g + H_I$	J/m²		
Е	upward irradiance	$E = E_g + E_l$	W/m <sup>2</sup>		
Н	upward radiant exposure for a specified time interval	$H = H_g + H_I$	J/m²	W∙h/m²	Change of units
Е	direct solar irradiance normal to the apparent solar zenith angle		W/m²	DNI	Direct Normal Irradiance
E <sub>0</sub>	solar constant		W/m <sup>2</sup>		
E <sub>g</sub> h	global irradiance; hemispherical irradiance on a specified, in this case horizontal surface.*	$E_g = E \cos \theta_h + E_d$	W/m²	GHI	Global Horizontal Irradiance
E <sub>g t</sub>	global irradiance; hemispherical irradiance on a specified, in this case tilted surface.*	$E_{g} = E \cdot \cos \theta_{t} + E_{d} + E_{r} + E_{r} + E_{r}$	W/m <sup>2</sup>	POA	Plane of Array
E <sub>d</sub>	downward diffuse solar radiation		W/m <sup>2</sup>	DHI	Diffuse Horizontal Irradiance
E <sub>1</sub> , E <sub>1</sub>	upward / downward longwave irradiance		W/m <sup>2</sup>		
Er	reflected solar irradiance		W/m <sup>2</sup>		
E*	net irradiance	E* = E - E	W/m <sup>2</sup>		
$T_{surface}$	equivalent blackbody radiative temperature of the surface**		oC.		
T <sub>sky</sub>	equivalent blackbody radiative temperature of the sky**		°C		
SD	sunshine duration		Н		

 $\theta$  is the apparent solar zenith angle  $\theta_h$  relative to horizontal,  $\theta_t$  relative to a tilted surface g = global, I = longwave, t = tilted \*, h = horizontal\*

<sup>\*</sup> distinction horizontal and tilted from Hukseflux,

<sup>\*\*</sup> T symbols introduced by Hukseflux,

<sup>\*\*\*</sup> contributions of  $E_d$   $_t$  and  $E_r$   $_t$  are  $E_d$  and  $E_r$  both corrected for the tilt angle of the surface



**Table 8.5.1** Calibration hierarchy for pyrgeometers with 150° field of view angle

#### **WORKING STANDARD IR20 CALIBRATION AT PMOD / WRC DAVOS**

Calibration of working standard IR20 (180° field of view angle) pyrgeometers traceable to WISG.

A typical uncertainty of S is 4.2 % (k = 2).

# CORRECTION OF (WORKING) STANDARD IR20 CALIBRATION TO STANDARDISED REFERENCE CONDITIONS

Correction from "test conditions of the standard" to "reference conditions": No corrections are applied.

Reference conditions are: horizontal mounting, atmospheric longwave irradiance, clear sky nights, 20 °C.

#### **OUTDOOR IR02 WORKING STANDARD CALIBRATION AT HUKSEFLUX**

Calibration of working standard IR02 ( $150^{\circ}$  degrees field of view angle) pyrgeometer at Hukseflux

#### **INDOOR PRODUCT CALIBRATION**

Calibration of products, i.e. pyrgeometers of type IR02:

Indoor side by side comparison to a working standard IR02 pyrgeometer under an infra-red blackbody source

#### **CALIBRATION UNCERTAINTY CALCULATION**

ISO 98-3 Guide to the Expression of Uncertainty in Measurement, GUM Determination of combined expanded uncertainty of calibration of the product, including uncertainty of the working standard, uncertainty of correction, uncertainty of the method (transfer error). The coverage factor must be determined; at Hukseflux we work with a coverage factor k=2. Hukseflux specifies a calibration uncertainty of 00 (00 (00 (00 ).

ir02 manual v1301 37/43



# 8.4 Appendix on standards for classification and calibration

Unlike pyranometers, pyrgeometers are not subject to a system of classification. At Hukseflux we distinguish between normal pyrgeometers, like model IR02, and "research grade" pyrgeometers, like IR20 and IR20WS. The term "research grade" is used to indicate that this instrument has the highest attainable specifications.

## 8.5 Appendix on calibration hierarchy

Hukseflux pyrgeometers are traceable to the World Infrared Standard Group (WISG). WISG is composed of a group of pyrgeometers. The calibration hierarchy of Hukseflux IR02 is from WISG through Hukseflux internal calibration procedures. The calibration of the IR02 working standard involves outdoor comparison at Hukseflux of the IR02 working standard to a working standard of a higher level, a pyrgeometer of model IR20 calibrated against the WISG. IR02 pyrgeometers are calibrated using an indoor procedure under an infra red source (blackbody).

The WISG group of instruments is maintained by World Radiation Center (WRC), in Davos Switzerland. An absolute sky-scanning radiometer provides the absolute longwave irradiance reference. Comparisons between the reference and the WISG are performed on a regular basis to maintain the WISG and supervise its long-term stability. It is essential that these intercomparisons take place under various sky conditions, but the predominant condition is a clear sky, which means that the validity of WISG calibration is a clear-sky spectrum. Typical exchange between pyrgeometer and sky is in the -70 to  $-120 \text{ W/m}^2$ .

ir02 manual v1301 36/43



# 8.9 EC declaration of conformity



We, Hukseflux Thermal Sensors B.V.

Elektronicaweg 25 2628 XG Delft The Netherlands

in accordance with the requirements of the following directive:

2004/108/EC The Electromagnetic Compatibility Directive

hereby declare under our sole responsibility that:

Product model: IR02

Type: Pyrgeometer

has been designed to comply and is in conformity with the relevant sections and applicable requirements of the following standards:

Emission: EN 61326-1 (2006) Immunity: EN 61326-1 (2006) Emission: EN 61000-3-2 (2006)

Emission: EN 61000-3-3 (1995) + A1 (2001) + A2 (2005).

Kees VAN DEN BOS

Director

Delft

April 10, 2013

ir02 manual v1301



